




Replace existing signal heads with 12" 3-section heads, and add supplemental signal head on span pole.



Restripe pavement markings and add lane-use signs to clarify intended lane-use.



Route 5 Corridor Study
Wallingford, CT



Short-Term Improvement Concept Plan
Route 5 (North Colony Road) at Route 71 (Old North Colony Road)
June 2020

